EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1 ⁻	88766	((force load stress strain compress\$4 tensi\$3) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR .	ON	2007/03/09 14:16
L2	97	1 and fishing near3 line.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 15:03
L3	0	1 and fishing near3 line near3 test4. clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 12:00
L4	48	1 and (fishing near3 line near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 12:40
L5	17	4 and (standard predetermined treshlod referece).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 14:19
Ŀ6	17	4 and adjust\$4.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 14:06
L7	63	1 near4 fishing .clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 14:15
L8	20	7 and (force drag load stress strain compress\$4 tensi\$3) near3 (adjust\$4 control\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 14:39
L9	9	8 and (standard predetermined treshlod referece).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 14:19
L10	.111	(73/862.393).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/09 14:40
L11	3	10 and fishing near3 line.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 14:40
L12	54	2 and (gauge needel indicat\$4).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 15:04

EAST Search History

L13	54	2 and (gauge needle indicat\$4).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 15:05
L14	0	3 and spring.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 15:04
L15 .	0	3 and spring	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/09 15:04